

## **BRAINWARE UNIVERSITY**

## Term End Examination 2021 - 22 Programme – Diploma in Mechanical Engineering Course Name – Principle of Machine Tool Course Code - DME603 (Semester VI)

Time allotted: 1 Hrs.15 Min. Full Marks: 60 [The figure in the margin indicates full marks.] Group-A (Multiple Choice Type Question) 1 x 60=60 Choose the correct alternative from the following: (1) Flank wear occurs mainly on the a) Nose part, front relief face and side relief face b) Face of the cutting tool at a short distance of the cutting tool from the cutting edge c) Cutting edge only d) Front face only (2) Glazing in grinding wheels cutting capacity. a) Has no effect on b) Increase c) None of these d) Decrease (3) Tool signature consists of elements. a) 3 b) 4 c) 5 d) 7 (4) Angle between the rake face flank of tool and perpendicular line drawn from cutting point to base of tool is known as: a) Side rake angle b) Side relief angle c) End relief angle d) Back rake angle (5) For large positive back rake angle, tool will be a) Weaker b) Stronger c) Smoother d) Harder (6) Positive rake angle is given for machining of: a) Brittle material b) Ductile material

(7) Which of the following will give maximum chip flow during machining?

c) Both hard and soft material

d) Carbide material

a) Hard material	b) Ductile material	
c) Brittle material	d) All of the mentioned	
(8) For machining of carbide material which of the fol	lowing tool will be preferred?	
a) Large positive rake angle tools	b) Large negative rake angle tools	
c) Zero rake angle tools	d) Small point angle tools	
(9) Thermal cracking of tools occurs at		
a) Low temperature	b) High temperature	
c) Low cutting speed	d) High cutting speed	
(10) What is the maximum allowed value of VB in mm piece for rough machining?	for HSS tool used with cast iron work	
a) 0.5	b) 1.5	
c) 2	d) 2.5	
(11) If a percentage of cobalt in Tungsten carbide tool increases, then toughness of tool will		
a) Increase	b) Decrease	
c) Remains Constant	d) First increase then decrease	
(12) Which cutting condition affects the cutting temperature predominantly?		
a) depth of cut	b) cutting speed	
c) feed	d) cross feed	
(13) The cutting tool removes the metal from workpiece	e in the form of	
a) solid blocks	b) powder	
c) chips	d) liquid	
(14) The angle between side cutting edge and end cutting	ng edge is called as	
a) approach angle	b) nose angle	
c) side relief angle	d) end relief angle	
(15) Tool life in orthogonal cutting is		
a) more than the tool life in oblique cutting	b) less than the tool life in oblique cutting	
c) equal to the tool life in oblique cutting	d) cannot say	
(16) The ascending order of evolution of materials used	for making the cutting tools is	
a) bronze – stone – steel – iron	b) iron – steel – bronze – stone	
c) stone – bronze – iron – steel	d) bronze – stone – steel – iron	
(17) The built up edge in cutting tools can be eliminated	l by	
a) Fast cutting speed	b) Higher rake angles	
c) High pressure cutting fluid	d) All the mentioned above	
(18) Horizontal force exerted by tool on work piece is k	cnown as	
a) Cutting force	b) Frictional resistance	
c) Backing up force	d) Shear force	
(19) Which of the following assumption is not valid for	merchant circle diagram	
a) Continuous Chips	b) Discontinuous chips	
c) Cutting edge remains sharp	d) No built up edge	
(20) Which of the following will have a maximum amount of chips during machining		
a) Ductile material	b) Brittle material	
c) Cast iron	d) carbide material	

(21) Continuous enips with built up eage are formed	during machining of
a) brittle metals	b) ductile metals
c) hard metals	d) soft metals
(22) In machining of a workpiece, the material is rem	noved by
a) drilling action	b) melting action
c) shearing acting	d) using brittleness of the material
(23) Feed is measured in units of	
a) length/revolution	b) degree/revolution
c) length	d) velocity
(24) In CNC systems multiple microprocessors and p	programmable logic controllers work
a) in parallel	b) in series
c) one after the other	d) for 80% of the total machining time
(25) In how many ways CNC machine tool systems of	can be classified?
a) 2	b) 3
c) 4	d) 5
(26) In part programming, interpolation is used for ob-	btaining trajectory
a) helicoidal	b) pentagonal
c) triangular	d) zig-zag
(27) For machining a mild steel workpiece by a high is	speed steel tool, the average cutting speed
a) 5 m/min	b) 10 m/ min
c) 15 m/min	d) 30 m/min
(28) The machining of titanium is difficult due to	
a) high thermal conductivity of titanium	b) chemical reaction between tool and work
c) low tool-chip contact area	d) high tool-chip contact area
(29) In machining metals, surface roughness is due to	)
a) feed marks or ridges left by the cutting tool	b) fragment of built up edge on the machined surface
c) cutting tool vibrations	d) all of the mentioned
(30) Ceramic tools are fixed to a tool body by	
a) soldering	b) brazing
c) welding	d) clamping
(31) High speed steel tools retain their hardness upto	a temperature of
a) 250	b) 350
c) 500	d) 900
(32) Which of the following parameters govern the vertical formation?	alue of the shear angle in continuous chip
a) true feed	b) chip thickness
c) rake angle of the cutting tool	d) all of the mentioned
(33) In metal machining, the zone where the heat is g moving chip and the tool face is called	generated due to friction between the
a) friction zone	b) work tool contact zone

c) secondary shear zone	d) primary shear zone
(34) End of the work piece can be support	ted by using
a) Headstock	b) Tailstock
c) Tool Post	d) chuck
(35) Which of the following have a live of	centre?
a) Tail stock	b) Headstock
c) Tool post	d) chuck
(36) Which of the following is used to gir	ve power feed during cutting of threads?
a) Rack and pinion	b) Planer mechanism
c) Quick return mechanism	d) Using spilt nut
(37) Self centered chuck has number	of jaws.
a) 10	b) 2
c) 3	d) 1
(38) What are thread chasers?	
a) Multipoint cutting tool	b) Single point cutting tool
c) A work holding device	d) anyone of the mentioned
(39) Which of the following is the part of	f feed mechanism?
a) spindle gear	b) tumbler gear unit
c) apron mechanism	d) all of the mentioned
(40) Table top drilling machine can be ca	tegorized as
a) general purpose drilling machine	b) specific purpose drilling machine
c) can't say anything	d) None
(41) Multi spindle drilling machine can b	e categorized as
a) general purpose drilling machine	b) special purpose drilling machine
c) can't say anything	d) None
(42) Grinding can be performed by	_
a) using faceplates or angle plates	b) using chucks
c) special attachments	d) None
(43) Which of the following is included i	n basic machine tools?
a) lathe machine	b) production milling machine
c) production drilling machine	d) None
(44) CNC machining centre does all the v	work
a) milling machine	b) drilling machine
c) both milling and drilling machine	d) double numerical control
(45) The main parts of shaper are	_
a) base and body	b) ram and tool head
c) crossrail and body	d) all of the mentioned
(46) Drive mechanism consists of	
a) main drives	b) the gear box
c) quick return mechanism	d) all of the mentioned
(47) The thickness of the chip is	when the tooth begins its cut in downmilling.
a) maximum	b) minium

c) 0	d) 2	
(48) is the speed at which the metal is removed	d by the tool from the work piece.	
a) feed	b) deepth of cut	
c) cutting speed	d) None	
(49) Which of the following represent the unit of cutt	ing speed?	
a) meter*minute	b) meter*meter*minute	
c) meter / minute	d) None	
(50) Which of the following is the unit of the feed?		
a) mm / minute	b) mm / revolution	
c) mm * minute	d) None	
(51) Which of the following represents the unit of metal removal rate?		
a) mm/revolution	b) mm*mm/revolution	
c) mm*mm*mm/revolution	d) None	
(52) For general purposes, ratio of the depth of cut to	the feed varies from	
a) 10:1	b) 1:10	
c) 0.868055555555555	d) 0.214583333333333	
(53) Which of the following process is not grouped un	nder metal removal process?	
a) boring	b) milling	
c) tumbling	d) rolling	
(54) In which type of metal removal process, grinding	g is included?	
a) conventional machining	b) abrasive process	
c) nontraditional machining	d) None	
(55) What is the function of the GUI(Graphical user i	nterface)?	
a) To control motion and speed	b) Converts program into the action of the driver	
c) To record the data from the sensor	<ul> <li>d) To understand the position of the tool according to the input program</li> </ul>	
(56) Sensors used in measurement systems are		
a) speed and position sensor	<ul> <li>b) consist of amplifier circuits, driving motors and ball lead screw</li> </ul>	
c) numerical control sensors	d) measurement sensors	
(57) In the block diagram of the CNC machine, data p	processing and control loop are a part of	
a) speed and position sensor	b) feedback system	
c) machine control unit	d) input device	
(58) Which does CNC stand for with respect to mach	ine related manufacturing?	
a) Computer Numb control	b) Computer Number control	
c) Computer Numerical control	d) Computerised Numerical controller	
(59) What is the full form of CAD?		
a) Computer aided Design	b) Computer arts Design	
c) Computer arts Designing	d) Computer assisted Design	
(60) The following diverts the power at right angles to	owards the driving wheels	
a) Torque tube	b) Transfer case	

d) Differential